

## Fairway Buoy No.5 – Unlit

Masters, Warranted Pilots, Holders of Pilotage Exemption Certificates, Owners, Operators and Agents of all Vessels navigating within Dublin Port are hereby notified that starboard fairway lateral mark Buoy No.5 is reported as unlit.



Extract of BA1447 Plan B - Not For Navigation © Crown Copyright. Reproduced by permission of the Controller of His Majesty's Stationery Office and the UK Hydrographic Office [www.GOV.UK/UKHO](http://www.GOV.UK/UKHO)

We will attend the buoy to repair/replace the light as soon as possible.

VTS will keep all vessels updated and advise of any relevant information on VHF Channel 12.

Captain Michael McKenna | Harbour Master | 23 February 2024

Masters, owners, agents, charterers, marinas, yacht clubs and recreational boaters should ensure that the contents of this notice are made known to the persons in charge of their vessels or craft. All notices to mariners can be found at [www.dublinport.ie/information-centre/notice-to-mariners/](http://www.dublinport.ie/information-centre/notice-to-mariners/)



Dublin  
SafePort

Enhancing  
safety culture  
and practice,  
port-wide.