Dublin Port - Bathymetric Chart 04 - Q2 2022

A

B

North Bank Lighthouse

A0 Charts



KEY PLAN

LEGEND

-0.5 m
0.5 m
1.5 m
2.5 m
3.6 m
4.7 m
5.8 m
6.9 m
8.0 m
9.0 m
10.1 m
11.2 m
12.2 m
13.3 m

Maintenance Dredge Design
Navigation Buoys

0 50.0 100.0 200.0 m

GENERAL NOTES

Soundings: Navigation Depths - Shoal Bias
Meters below datum

Contours: 1 meter interval

Datum: Chart Datum (OD Malin - 2.51 m)
Projection: Geographic - WGS84

Survey Location: Dublin Port
Survey method: Multibeam echosounder
Survey Date: **04, 05, 06, 07 and 13 of July 2022**

HydroMaster Ltd
7 Howley court, Dublin Road
Oranmore, Co. Galway.
Ireland
T +353 860891047
E info@hydromaster.ie

Date:	Rev:	Description:	Drawn By:
27/07/2022	0	Issue	MT

COMHLACHT CHALAFORT ÁTHA CLIATH
DUBLIN PORT COMPANY

Drawing information

Client: Dublin Port Company

Project: Dublin Port Quarter bathymetric surveys

Drawing title: Bathymetric Chart 04 - Q2 2022

Job No.: 2207_DP_Q2_001	Scale: A0 @1:2000
Drawing date: 27/07/2022	Drawn by: MT